

PO Number	BPS/BSR32178-3
Supplier	Louis Suzhou
Supplier QA Notes	* Check that each master carton includes shipping marks on each master carton that includes: PO number, SKU value, abbreviated product name, carton configuration (units per case), case dimensions, net weight, gross weight, and country of manufacture (ie. Made in China) . Using metric measurements. * If the destination of the shipment is an Amazon FBA fulfilment centre, each master carton will have one FBA case label. * If the destination of the shipment is our 3PL warehouse (Warehouse Republic), each master carton will have one warehouse barcode label. Additionally, there will be one simplified visual sticker on each master carton, which shows the product shape, colour, and product size. * Place one simplified visual sticker on each master carton, which shows the product shape, colour, and product size. * A product 'insert' will be included inside the packaging for each unit.
Freight Forwarder	Flexport
Shipment ID	636161

Product	Merchant SKU	QA Notes
STNDRD Plant Stand (10", 1-Pack) https://www.amazon.com/dp/B07MP5QW5Q	L0-QVYU-20Q6	* STNDRD logo is printed onto one part of the plant stand. The size is approximately 5x1cm and is positioned on the lower-right edge of the piece. * Look out for splinters in the bamboo that could cause personal injury, or give an unfinished look. * Common quality issues associated with the bamboo material: cracks, scratches, color stains, dirt marks, peeling paints. * Scannable barcode on the packaging. * Includes insert, tools, screws, feet pads, and instructions. * No wobble when assembled. * Sits evenly on the ground. * Strong joints. Pull test to be sure the joints are strong. * Screw threads easily.

Product	Merchant SKU	QA Notes
STNDRD Shoe Rack (1-Pack) https://www.amazon.com/dp/B076V3NDL8	F6-YY28-JHOR	* Look out for splinters in the bamboo that could cause personal injury, or give an unfinished look. * Common quality issues associated with the bamboo material: cracks, scratches, color stains, dirt marks, burn marks, peeling paints. * Consistent finishing. Look for unfinished areas. * Drop test. * Insert and instructions properly in the packaging. * Cracks near predrilled holes * Sturdy when assembled * Joints are strong. Pull test. * Tools, feet pads, and screws in packaging. * Scannable barcode on the packaging.